

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2025

Submitted Date:

09/24/2025

Document Number:

714300276

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Dan		danpeterson@chevron.com	
, Inspections		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Chevron Inspections</a>
Cholas, Nick		nick.cholas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
491270	SPILL OR RELEASE	CL	08/29/2025		-	Five Rivers K04-21D	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 491270/ Remediation Project No 29068. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 491270 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Per Form 19 Spill date of discovery is 08/28/2025. Any spill excavation conducted at the Spill location has been backfilled.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #29068 with a workplan and timeline for remediation of Spill ID 491270 Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)		
	Comment	No E&P waste was observed stored on location.				
	Corrective Action	Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal.			Date:	

**Spill/Remediation:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300277	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250963</a>