

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2025

Submitted Date:

09/26/2025

Document Number:

719000698

FIELD INSPECTION FORM

Loc ID: 482935 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES LLC
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, GENERAL		hwilli@swbell.net	
,		glennstevens95@gmail.com	
Labowskie, Steve		steve.labowskie@state.co.us	

General Comment:

Inspection Report Summary
On 9/26/25 | Inspector Charles Garcia conducted an on-site FOLLOW UP inspection. Location: 1-33 SWNW M&M TANK BATTERY Operator: WILLIFORD RESOURCES LLC FACILITY ID#482938 County: LaPlata

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Horizontal Heated Separator	# 1				
Comment:	SEPARATOR ON LOCATION APPEARS TO BE OUT OF SERVICE AND IS OPEN ON ONE END WILDLIFE CAN ENTER. ALSO HAS OIL INSIDE LEAKING AND IMPACTING SOIL FLAR CAMARA ALSO SHOWS GAS LEAK ON UNIT IF NOT IN USE REMOVE FROM LOCATION SEE LOCATION PICTURES				
Corrective Action:	Install or repair wildlife protection equipment. PER RULE 608.a.(13) Unnecessary equipment COMLPY WITH RULE 606 CLEAN UP IMPACTED SOIL AROUND SEPARATOR rule1002.f			Date:	12/26/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	PBV FIBERGLASS		37.133600,-108.109100	
Comment:	OPEN TOP GREEN FIBER GLASS TANK ON LOCATION HAS NO WILD LIFE NETTING OR PLACARDS CRUD OIL CAN NOT BE STORED IN A OPEN TOP TANK SEE LOCATION PICTURES					
Corrective Action:	Install or repair wildlife protection equipment. PER RULE 608.a.(13) OR REMOVE UNUSED EQUIPMENT COMLPY WITH RULE 606				Date:	10/03/2025

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000699	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7256658
719000700	GAS LEAK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7256659