

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404372507

Date Received:  
09/29/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 707 17TH STREET SUITE 2975  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Trujillo, Helen</u>		<u>notices@bayless-cos.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 707801742  
Inspection Date: 07/16/2025 FIR Submit Date: 08/05/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720  
Address: 707 17TH STREET SUITE 2975  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312955

Location Name: COTTONWOOD GULCH FED-68N91W Number: 25SENE County: \_\_\_\_\_  
Qtrqr: SENE Sec: 25 Twp: 8N Range: 91W Meridian: 6  
Latitude: 40.624467 Longitude: -107.546230

FACILITY - API Number: 05-081-00 Facility ID: 312955

Facility Name: COTTONWOOD GULCH FED-68N91W Number: 25SENE  
Qtrqr: SENE Sec: 25 Twp: 8N Range: 91W Meridian: 6  
Latitude: 40.624467 Longitude: -107.546230

CORRECTIVE ACTIONS:

**1** CA# 206839

Corrective Action: Maintain containment to ensure spill or released materials will be maintained with containment structure.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Built up containment structure

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 206840

Corrective Action: Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Removed debris from around vents on pressure safety devices

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 206841

Corrective Action: Remove debris

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Removed debris

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 206842

Corrective Action: Install caps or plugs

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Installed cap and/or plugs

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 206843

Corrective Action: Remove or put into use and provide adequate secondary containments.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Corrected secondary containments

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Robert L. Bayless, Producer LLC addresses all the compliance issues on the document number 707801742

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Trudy Cundiff

Signed: \_\_\_\_\_

Title: Regulatory Compliance

Date: 9/29/2025 3:56:23 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404372507	FIR RESOLUTION SUBMITTED
404372530	Inspection Photos

Total Attach: 2 Files