

State of Colorado
Energy & Carbon Management Commission



Document Number:
404376359

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
10/01/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10722

Name of Operator: KTM OPERATING LLC

Address: 2851 JOHNSTON ST PMB 550

City: LAFAYETTE State: LA Zip: 70503

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Hecht, Jaime

832-531-1711

jaime.hecht@dynacloud.io

Vincent, Kenny

(337) 654-9404

kvincent@reagan.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 706700322

Inspection Date: 03/22/2023

FIR Submit Date: 03/24/2023

FIR Status: _____

Inspected Operator Information:

Company Name: KTM OPERATING LLC

Company Number: 10722

Address: 2851 JOHNSTON ST PMB 550

City: LAFAYETTE State: LA Zip: 70503

LOCATION - Location ID: 309616

Location Name: CRAIG-613S55W Number: 34SWNE County: LINCOLN

Qtrqtr: SWNE Sec: 34 Twp: 13S Range: 55W Meridian: 6

Latitude: 38.875710 Longitude: -103.543150

FACILITY - API Number: 05-073- -00 Facility ID: 294991

Facility Name: CRAIG Number: 7-34

Qtrqtr: SWNE Sec: 34 Twp: 13S Range: 55W Meridian: 6

Latitude: 38.875710 Longitude: -103.543150

CORRECTIVE ACTIONS:

1 CA# 168812

Corrective Action:

Date: 09/25/2023

Rule 417f. All Wells will maintain mechanical integrity. All Wells which lack mechanical integrity, as determined through a mechanical integrity test, or other means, will be repaired or Plugged and Abandoned within 6 months. If an Operator has performed a mechanical integrity test within the 2 years required for Shut-in Wells or the 30 days required for Temporarily Abandoned Wells by this Rule, the Operator will have 6 months from the date of the unsuccessful test to make repairs or Plug and Abandon the Well. If the Operator has not performed a mechanical integrity test within the required time frames in Rules 417.b.(1) & c.(1), the Operator will not be given an additional 6 months in the event of an unsuccessful test.

Response: CA COMPLETED

Date of Completion: 08/30/2023

Operator Comment:

MIT was conducted 8/30/2023 and passed (Form 21 Document No. 403509675).

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specialist

Date: 10/1/2025 2:38:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404376359	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files