

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2025

Submitted Date:

09/26/2025

Document Number:

709100561

FIELD INSPECTION FORM

Loc ID 316940 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 11 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		gfritzler@firesources.com	
Grace Rollins		grace.rollins@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections
Krystal Heibel		krystal.heibel@state.co.us	
Anthony Dunnam		anthony.dunnam@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233352	WELL	PR	10/01/2021	OW	121-05388	BEN 1	PR
316940	LOCATION	AC			-	BEN-63S53W 30SENE	AC

General Comment:

On September 24, 2025, ECMC Environmental Unit Staff Krystal Heibel, Anthony Dunnam, and Grace Rollins inspected the BEN-63S53W 30SENE location (Location ID 316940), the Ben 1 well (API 05-121-05388), and the Ben 1 pits (Facility IDs: 107605 and 107606).

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	Oil and gas facility signage present		
Corrective Action:			Date:
Type			
Comment:	Signage observed to be faded and unable to read.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 10/01/2025
Emergency Contact Number:			
Comment:	Emergency contact number on tanks observed to be faded and unable to be seen from a distance.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 10/01/2025
Good Housekeeping:			
Type			
Comment:	Trash and unused equipment observed on location		
Corrective Action:	Comply with Rule 606		Date: 10/01/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Comment:	Hydrocarbon stained soil observed next to tanks under pipes (See photo 4) next to unlabeled container (see photo 14).		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.. Per Rule 912.a.(1-2): Immediately upon discovering any Spills or Releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas that meet the criteria of Rules 912.b.(1).H, I, or J, regardless of size or volume, Operators will control and contain the Spill or Release to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources. Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered.		Date: 09/27/2025
Comment:	Active hydrocarbon spill observed at wellhead		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.. Per Rule 912.a.(1-2): Immediately upon discovering any Spills or Releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas that meet the criteria of Rules 912.b.(1).H, I, or J, regardless of size or volume, Operators will control and contain the Spill or Release to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources. Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. ECMC Staff notified Nathan Fritzler while at the Scott Federal 1 (API 121-05180) location.		Date: 09/25/2025
In Containment: No			
Comment:	Emergency contact number on tanks not visible from a distance and are in need of repair.		
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	#		
Comment:	Open pipes observed throughout site.		
corrective date			

Corrective Action:	Either remove unused equipment or securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	10/09/2025
Type:	#		
Comment:	Unlabeled containers observed to be covered in hydrocarbons located at pump jack.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention.	Date:	10/03/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Large burrows observed at the location. Berms inadequate around tanks, vertical heater treater, and partially buried vessel.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1) and per Rule 912.d.(1).			Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 233352 Type: WELL API Number: 121-05388 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 316940 Type: LOCATION API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404370164	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7256101
709100562	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7256086