

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2025

Submitted Date:

10/01/2025

Document Number:

716301577

**FIELD INSPECTION FORM**

Loc ID 307268 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>
Sanchez, Chris		chris.sanchez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217325	WELL	PR	07/13/1998	CBM	071-06101	HORN SPRING GAS COM 3-32-33	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."  
THIS INSPECTION IS OF THE DEHY. EQUIPMENT SPILL. ATTACHED TO THIS LOCATION DUE TO IT BEING THE CLOSEST FACILITY TO THE DEHY. EQUIPMENT. AT TIME OF INSPECTION DEHY. EQUIPMENT DOES NOT HAVE ITS OWN FACILITY ID #.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: SEE SPILLS SECTION FOR CORRECTIVE ACTION.

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

Other

Comment: THERE WAS A RESEASE OF E&P WASTE OR PRODUCED FLUIDS FROM A DEHYDRATOR TO THE NORTH OF LOCATION. SEE ATTACHED PHOTOS

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 10/02/2025

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Gas Meter Run

# 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Deadman # & Marked

# 3

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Dehydrator

# 2

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 3

Comment:

Corrective Action:

Date:

Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 217325 Type: WELL API Number: 071-06101 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Tuesday 10-1-2025 at approximately 09:39, I Tom Beardslee                      Conducted an on-site inspection an Evergreen Natural Resources location HORN                      SPRINGS GAS COM 3-32-33                      API# 05-071-06101 in Las Animas County Colorado.                      While there, I observed production operation.                      During this inspection the following possible compliance issues were observed:                      PHOTO 4, 5, 6 &amp; 7: IMAGE SHOWING THE SPILL AREA. THE BULK OF THE SPILL                      FLUID IS APP. 35' AROUND THE EQUIPMENT WITH SOME SPRAY REACHING OUT TO                      THE EAST AND SOUTH APP.50'.                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	10/01/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404376687	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263833</a>
716301578	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263831</a>