

# Inspection Photos

**09/26/2025**

**Operator:** BEEMAN OIL AND GAS INC # 7125

**Location ID:** 425419

**Inspection Document #:** 712300230

Moffat County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bret Grandbouche 24-02H Pad  
Location ID: 425419



09/26/2025  
160° S  
ECMC

**Photo 1.** Photo taken at the entrance of the Location.



09/26/2025  
258° W  
ECMC

**Photo 2.** Photo taken of the cut slope on the northwestern portion of the Location, facing west.



## Inspection Photos

Location Name: Bret Grandbouche 24-02H Pad

Location ID: 425419



**Photo 3.** Photo taken mid-slope of the cut slope on the western portion, facing southeast.



**Photo 4.** Photos 4-7 taken on the cut and fill slopes, illustrating a weed infestation of Scotch thistle (circled in red), which is over 6 feet in height across most of the Location. Other undesirable plant species include Bull thistle, Russian thistle, prostrate knotweed, houndstongue, and cheatgrass.

Inspection Photos



**Photo 5.** See comments under Photo 4; photo illustrates houndstongue seen on the cut/fill slopes.



**Photo 6.** See comments under photo 4.



Inspection Photos

Location Name: Bret Grandbouche 24-02H Pad

09/26/2025 Location ID: 425419

148° SE  
ECMC



Photo 7. See comments under Photo 4.

09/26/2025  
116° SE  
ECMC



Photo 8. Photos 8-9 taken of the fill slope and topsoil stockpile. Photo illustrates that the topsoil stockpile is dominated primarily by Scotch thistle (red circle).



Inspection Photos

Secret Grandbouche 24-02H Pad  
Location ID: 425419



Photo 9. See comments under Photo 8.



Photo 10. Photo taken of an example of trash (netting) found on Location.



Inspection Photos

Site: Grandbouche 24-02H Pad  
Location ID: 425419



**Photo 11.** Photo taken at the separator equipment. Photo illustrates fluids inside of secondary containment.



**Photo 12.** Photos 12-13 taken at the separator equipment along the outside eastern perimeter, illustrating stained soils.



Inspection Photos



Photo 13. See comments under Photo 12.



Photo 14. Photos 14-15 taken at the wellhead, illustrating stained soils.



Inspection Photos



Photo 15. See comments under Photo 14.



Photo 16. Photo taken of secondary containment at the wellhead, illustrating wildlife protection BMPs are no longer functioning to prevent access to wildlife.