

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404384636

Date Received:  
10/08/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

9 of 9 CAs from the FIR responded to on this Form

9 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 707 17TH STREET SUITE 2975  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
		<a href="mailto:notices@bayless-cos.com">notices@bayless-cos.com</a>
		<a href="mailto:j75rober@blm.gov">j75rober@blm.gov</a>
		<a href="mailto:kris.neidel@state.co.us">kris.neidel@state.co.us</a>
		<a href="mailto:htrujillo@bayless-cos.com">htrujillo@bayless-cos.com</a>
		<a href="mailto:steve.freese@state.co.us">steve.freese@state.co.us</a>
		<a href="mailto:aaron.trujillo@state.co.us">aaron.trujillo@state.co.us</a>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 712300137  
Inspection Date: 05/28/2025 FIR Submit Date: 07/31/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720  
Address: 707 17TH STREET SUITE 2975  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 316764

Location Name: DRY CREEK FEDERAL-65N88W Number: 14NENE County: \_\_\_\_\_  
Qtrqr: NENE Sec: 14 Twp: 5N Range: 88W Meridian: 6  
Latitude: 40.395501 Longitude: -107.222268

**FACILITY** - API Number: 05-107-00 Facility ID: 316764

Facility Name: DRY CREEK FEDERAL-65N88W Number: 14NENE  
Qtrqr: NENE Sec: 14 Twp: 5N Range: 88W Meridian: 6  
Latitude: 40.395501 Longitude: -107.222268

**CORRECTIVE ACTIONS:**

**1** CA# 206663

Corrective Action: Comply with Rule 603.o.

Date: 08/08/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Built up the secondary containment berm surround the tank on the western portion of the location

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 206664

Corrective Action: Remove and properly dispose of impacted material pursuant to Rule 912.a. Clean/remediate impacts to Table 915-1 cleanup concentrations.

Date: 08/07/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Removed and properly disposed of impacted material pursuant to Rule 912.a. Clean/remediated impacts to Table 915-1 cleanup concentrations.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 206665

Corrective Action: Maintain fencing on Location.

Date: 08/29/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Maintained the fencing around of location

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**4** CA# 206666

Corrective Action: Comply with Rule 605.e.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Installed new sign on the well location

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**5** CA# 206667

Corrective Action: Comply with Rule 902.b.- install covers or other BMPs to prevent wildlife access to the tank equipment.

Date: 08/07/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Installed covers or other BMP's to prevent wildlife access to the tank equipment

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

6 CA# 206668

Corrective Action: Comply with Rules 1002.c and 1002.f and implement BMPs to protect the stockpile from erosion, degradation, sediment transport and weed establishment.

Date: 08/08/2025

If the stockpiled materials are not necessary, materials require removal pursuant to Rule 606.a.

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Implemented BMPs to protect the stockpile from erosion, degradation, sediment transport and weed establishment. Materials not necessary have been removed

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

7 CA# 206669

Corrective Action: Comply with Rule 606.

Date: 08/08/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Removed the weeds from location

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

8 CA# 206670

Corrective Action: Comply with Rule 606.

Date: 08/08/2025

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Removed trash, debris and unused equipment from location throughout location

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

9 CA# 206671

Corrective Action: Comply with Rule 1002.f.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 10/08/2025

Operator Comment: Implemented BMP's to protect the stockpile from erosion, degradation, sediment transport and weed establishment on location

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Robert L. Bayless, Producer LLC has taken care of all the compliance issues regarding Field Inspection

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Trudy Cundiff

Signed: \_\_\_\_\_

Title: Regulatory Compliance

Date: 10/8/2025 4:16:30 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404384636	FIR RESOLUTION SUBMITTED
404384667	Photos

Total Attach: 2 Files