


Looking at spill location and spill response area. Soil stockpiles remain on location. Soil with gray staining is visible on the ground surface outside of the excavations. Orange construction fencing surrounds the perimeters of the open excavations.



Looking at an excavation Operator personnel previously indicated was opened for flowline repairs. Free product and a petroleum hydrocarbon sheen are visible on groundwater within the excavation. Stained soil is visible on the excavation sidewalls.



Looking at the spill location. The excavations remain open.



Frederick, CO, United States



Lat 40.123517, Long -105.013715
10/09/2025 12:15 PM GMT-06:00
ECMC : Environmental Inspection

77°F

1.7 mph

4899.05 ft

5.87 m

158° SE

Free product is visible on groundwater within the excavation. Stained soil is visible on the excavation sidewalls. Flowline is visible protruding from the excavation.






Free product is visible on groundwater within the excavation. Stained soil is visible on the excavation sidewalls. A small, unmarked soil stockpile is visible within the orange construction fencing. No wildlife protection equipment (e.g. bird netting) is visible on location.






An unmarked soil stockpile with no stormwater BMPs is visible adjacent to an open excavation.






Frederick, CO, United States

Lat 40.123451, Long -105.013734
10/09/2025 12:18 PM GMT-06:00
ECMC : Environmental Inspection

 1.7 mph  4901.61 ft  3.72 m




 77°F  338° N






Areas of gray staining are visible within the unmarked soil stockpile.







Frederick, CO, United States

Lat 40.123473, Long -105.013677
10/09/2025 12:18 PM GMT-06:00
ECMC : Environmental Inspection

 1.7 mph  4903.05 ft  3.33 m




 77°F  75° E






The stockpile marked "contaminated" remains on location. A liner is visible but has been compromised by holes/tears; soil has spilled outside of containment.





Frederick, CO, United States

Lat 40.123639, Long -105.013781
10/09/2025 12:20 PM GMT-06:00
ECMC : Environmental Inspection




 1.7 mph  4901.08 ft  3.74 m  77°F  134° SE




Underground utility flags which read "KP Kauffman" are visible west of the location. An area of ground disturbance is visible on the hillside, in the location at which a backhoe was observed on 10/03/2025.





Frederick, CO, United States

Lat 40.123475, Long -105.014594
10/09/2025 12:23 PM GMT-06:00
ECMC : Environmental Inspection

 1.7 mph  4905.61 ft  3.45 m

 77°F  180° S

