



**Inspected Facilities**

Facility ID: 241904 Type: WELL API Number: 123-09695 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Si; valves appear to be in the closed position.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

### Optical Gas Imaging Survey

Survey Type: Routine

Current Operations:    Production    Workover    Flowback    Referred to APCD

GPS(entrance of location): Lat: 40.113800                      Long: -104.942500

Wind: Calm    Speed: 2 (mph)    Direction From: SSW    Weather: Clear    Temperature: 56 (F)

Assisting Staff: Brittani Santistevan                      Camera #: \_\_\_\_\_

Visible Smoke                       Referred to CDPHE

Times Surveyed    Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:30	AM	10:35	AM	Wellhead(s)

Comment: it appears to be a release of emissions at the wellhead. See attached photo and video.

Corrective Action: Comply with Rile 608.e.                      Date: 10/09/2025

### ECMC Comments

Comment	User	Date
<p><a href="#">ECMC Audit Report Summary</a>  <b>WEATHER CONDITIONS:</b> sunny, dry ground.                      On Wednesday, October 8, 2025 at approximately 1030, I, Inspector Brittani Santistevan, conducted an on-site inspection at FIRESTONE 'C' WELL #1 (KP Kauffman Company INC), at                      API #: 05-123-09695 in WELD COUNTY, Colorado.                      While there, I observed a shut-in wellhead.                      During this inspection the following possible compliance issues were observed:                      1. It appears to be a release of emissions at the wellhead. Securely fasten or seal all valves, pipes, fittings, and vessels, and inspect at regular intervals, and maintain in good mechanical condition Per Rule 608.e. (Corrective Action Date: October 9, 2025) See attached photo #2 and video.</p> <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the audit report.</p>	santistb	10/08/2025

### Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404384172	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272562</a>
714202570	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272551</a>
714202571	Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272552</a>