

WELL NAME: NEW ELK 25-14, API #: 071-09537, INSP. # 716301654



PHOTO 1: API # ON POSTED WELL SIGN IS INACCURATE. **POST SIGN PER RULE 605. CA DATE 11-23-2025.**



Network: Oct 23, 2025 at 10:14:36 AM MDT  
Local: Oct 23, 2025 at 10:14:36 AM MDT  
+37.137373,-104.947702  
Las Animas County  
Altitude:2276.5meters  
Speed:0.0km/h

**PHOTO 2: LOCATION.**



Network: Oct 23, 2025 at 10:18:52 AM MDT  
Local: Oct 23, 2025 at 10:18:52 AM MDT  
+37.137172,-104.948068  
Las Animas Count  
Altitude:2279.4mete  
Speed:0.4km/h

**PHOTO 3: UNUSED EQUIPMENT (1" RISER). REMOVE OR MARK RISER PER RULE 606. CA DATE 11-23-2025.**



**PHOTO 4: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 5: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 6: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 7: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**