

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



(C)

Well Name Hubbird-Boston 2 API Number 05 - 121 - 8203
Operator Baney Permit # _____
Location SEW 30-35-56W County Washington
Field 10250 Casino Inspector Binkley

AL/PA/DA Inspection Results: Well Status:
Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG _____ WO _____ PR _____ SI TA _____

=====
Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection 7-11-91

Comments: No Jack on #2 #4 PR 121-8227
(SEW 30) Tank Battery needs berm around tanks
4-300, VHT, OVD skim 20x20, P 40x200 clear

Violations: Yes No _____ Notice Sent: Yes No _____ Date Sent: 8991

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203
(303) 894-2109 FAX
(303) 894-2100

DENNIS R. BICKNELL
Director
JOHN R. STOWELL
Deputy Director
PATRICIA C. BEAVER
Technical Secretary

ROY ROMER
Governor

Barney Well Service Inc
P.O. Box 686
Sterling, CO 80751

RE: Lease Violation Notice

Lease : Hubbird - Boston
Field : Casino
County : Washington
Location: SE NW 30-35-56W

Gentlemen:

An inspection was made of the lease(s) shown above. The following marked conditions were observed to exist at the time of the inspection.

- Oil accumulation on the water in the retaining pit
- Tank Berm required or in need of repairs
- Covered skim pit or tank required
- Tank identification number missing or incorrect
- Wellhead sign required per rule 210(a), 604(c)
- Oil spilled at wellhead or tank battery
- Weeds, debris or waste material observed at site

REMARKS: Please submit status and intention for well #2.

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned within ten (10) days after receipt of this notice (Rule 328), and a written report or sundry notice submitted to this office within thirty (30) days after the work is accomplished, advising us of the date and manner in which the correction is made. Any person who fails to comply with this request is subject to the penalties as provided for under statute 34-5-121 of the Colorado Oil and Gas Conservation Act.

E.B. Binkley
Petroleum Engineer

Date of Inspection 7, 11, 91