

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2025

Submitted Date:

10/29/2025

Document Number:

719700265

FIELD INSPECTION FORM

Loc ID 305806 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282467	WELL	SI	11/01/2023	OW	123-23507	PAPPENHEIM 22-24	SI

General Comment:

*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	<p>Posted. OOSLAT applied at separator. *Refer to Emergency Contact Number section below.</p> <p>Prior audit: CORRECTIVE ACTION ITEM(s): During this audit the following possible compliance issue(s) were observed: Emergency contact number with Comapny & Well Name NOT posted at wellsite. Refer to Rule 605.d for guidance. *Post emergency contact number with Comapny & Well Name at wellsite. Comply with Rule 605.d. (30-days). CA date: 10/29/2025.</p>		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<p>This audit: *FIR Resolution Form FIRR doc. #404414220 asserts: Wellsite signage w/ Company, well name, Emergency # has been posted as of 10/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p>		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	<p>This audit: *FIR Resolution Form FIRR doc. #404377463 asserts: Overgrown vegetation around wellsite has been mitigated as of 10/02/2025. Operator provided photo for verification. See photo(s) #1, 2.</p>		
Corrective Action:			Date:
Type	WEEDS		
Comment:	<p>Prior audit: CORRECTIVE ACTION ITEM(s): During this audit the following possible compliance issue(s) were observed: Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. (30 days). CA date: 10/29/2025.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 282467 Type: WELL API Number: 123-23507 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
Prod valves shut.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at separator.
ECMC records last prod: 10/2023.
Form 5B on file. Defined Inactive: 10/31/2023. Approved.
Flowline shared w/ Pappenheim 32-24.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 01/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On WED 10/29/2025 at approximately 13:30 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at: Operator Name: NOBLE ENERGY INC Location Name: PAPPENHEIM-67N64W/24SEW Location ID: 305806 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>Audit observations: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>* While conducting this audit, the following prior possible compliance issues appear to be addressed: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: Refer to pg 2, "Signs/Marker" section of this report. *CORRECTIVE ACTION Item(s) RESOLUTION Comment: Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>*FIR Resolution Form FIRR doc. #404377463 asserts: Overgrown vegetation around wellsite has been mitigated as of 10/02/2025. Operator provided photo for verification. See photo(s) #1, 2.</p> <p>*FIR Resolution Form FIRR doc. #404414220 asserts: Wellsite signage w/ Company, well name, Emergency # has been posted as of 10/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/29/2025
<p>This is a WELL audit. (AMA: Alternate Method Audit). Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (305806, 305807, 305808). (Well(s): 3: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>*Follow-up to Field Audit Report doc. #719700138 dated 09/24/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404377463 dated 10/02/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404414220 dated 10/29/2025.</p>	evinsb	10/29/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700266	Audit phot(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7307694