

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2025

Submitted Date:

10/23/2025

Document Number:

716301654

FIELD INSPECTION FORM

Loc ID 309442 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
B WARD, GIENA		gward@ogrisop.com	All Inspections
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295031	WELL	PR	12/01/2024	CBM	071-09537	NEW ELK 25-14	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	PHOTO 1: API # ON POSTED WELL SIGN IS INACCURATE.		
Corrective Action:	POST SIGN PER RULE 605.	Date:	11/23/2025

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4,5,6 & 7: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002.,(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.	Date:	
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNUSED EQUIPMENT (1" RISER).		
Corrective Action:	REMOVE OR MARK RISER PER RULE 606.	Date:	11/23/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	FORM 4 IS ON FILE		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 295031 Type: WELL API Number: 071-09537 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/16/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: SUBMIT FORMS

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP TO INSP. DOC #698707783, CA'S HAVE NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED.</p> <p>ECMC Inspection Report Summary On Tuesday 10-23-2025 at approximately 11:44, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location NEW ELK 25-14</p> <p>API# 05-071-09537 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 1: API # ON POSTED WELL SIGN IS INACCURATE. POST SIGN PER RULE 605. CA DATE 11-23-2025. PHOTO 3: UNUSED EQUIPMENT (1" RISER). REMOVE OR MARK RISER PER RULE 606. CA DATE 11-23-2025. PHOTO 4,5,6 &7: THERE IS AN AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes COMPLY WITH RULE 1002,(2).D. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	10/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404402253	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293714
716301655	INSP PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293712