

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2025

Submitted Date:

11/04/2025

Document Number:

715801597

FIELD INSPECTION FORM

Loc ID 318577 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cullen Chew		cchew@kpk.com	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241641	WELL	SI	02/01/2024	OW	123-09430	UPRR 43 PAN AM B 10	SI

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Sign not legible, Install sign to comply with Rule 605.g. CA date 12-402025.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type			
Comment:	Dead vegetation need to be cut & removed from the wellsite per Rule 606. CA date 11-12-2025		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Fabricated steel pipe around the ancillary equipment

Corrective Action:

Date:

Type PUMP JACK

Comment: Hog fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel is shut off, meter box & transformers.		

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241641 Type: WELL API Number: 123-09430 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 11-4-2025 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 318577 API # 05-123-09430 Well name: UPRR 43 Pan Am B 10 County: Weld Weather: Partly Cloudy Temp: 64* Location: dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 606 housekeeping: Tall dead vegetation needs to be cut & removed. 650.g signs general: Sign is fade & needs to be updated. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	11/04/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801598	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317017