

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/05/2025

Document Number:

708907800

FIELD INSPECTION FORM

Loc ID 335112 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291727	WELL	SI	08/01/2025	GW	045-14501	PUCKETT 41D-25D	SI

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 291727 Type: WELL API Number: 045-14501 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: [Please refer to FORM 42 document # 404419771 submitted by operator on 11/03/2025](#)
 FORM 42 was submitted on 11/03/2025 with a start date of 11/03/2025 & a start time of 06:00 hours - Operator failed to give 48 hours advance written notice/not in compliance with CECMC Rule 405. I.

Corrective Action: [Submit notices in required time frame as per CECMC Rules](#) Date: 11/07/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 11/05/2025 at approximately 13:50 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of the QB ENERGY OPERATING LLC PUCKETT 41D-25D API # 05-045-14501 Location # 335112 in Garfield County Colorado.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - FORM 42 Notice of Plugging Operations not in compliance with CECMC Rule 405. I. - please refer to Inspected Facilities for further comments.</p> <p>This is a summary of desktop inspection/audit report.</p>	smelserw	11/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404424996	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319240
708907801	FORM 42 document # 404419771	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319239