

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/05/2025

Document Number:

713302324

**FIELD INSPECTION FORM**

Loc ID 318599 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241700	WELL	PR	03/01/2025	OW	123-09489	ELKHORN COMPANY B 7	PR

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	DEBRIS		
Comment:	DEAD overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	12/05/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric/automation disconnect, metal panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	post and wire		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	

Type: Ancillary equipment	# 4		
Comment:	automation/electric panels		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241700 Type: WELL API Number: 123-09489 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 03/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection, Location: Elkhorn Company B7 Operator: KPK API#: 123-09489 County: Weld While there, I observed well site with pumping unit. During this inspection the following possible compliance issues were observed:</p> <p>DEAD overgrown vegetation, Rule 606 corrective action date 12-5-2025 site pic 1&amp;2</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	11/05/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404425214	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319569</a>
713302325	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319564</a>