

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2025

Submitted Date:

11/13/2025

Document Number:

708907870

**FIELD INSPECTION FORM**

Loc ID 311552 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210761	WELL	PR	02/26/1987	GW	045-06519	HOAGLUND W-32-35	PR

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 210761 Type: WELL API Number: 045-06519 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	Date: <u>12/13/2025</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 11/13/2025 at approximately 16:29 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of TEP ROCKY MOUNTAIN LLC HOAGLUND W-32-35</p> <p>Location # 311552 in Garfield County Colorado.</p> <p>Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site &amp; in close proximity to NSO Habitat area.</p> <p>Location is within Rule 411a Surface Water External Buffer.</p> <p>Location is approximately 105 yards from the Colorado River.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - Well lacks wellbore diagram - Comply with rule 420 with a CA date of 12/13/2025</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of desktop inspection/audit report.</p>	smelserw	11/13/2025