





Network: Nov 14, 2025 at 9:21:14 AM MST  
Local: Nov 14, 2025 at 9:21:14 AM MST  
+37.290204,-104.8214  
Las Animas County  
Altitude: 2223.3 meters  
Speed: 0.0 km/h

**PHOTO 2: LOCATION.**




Network: Nov 14, 2025 at 9:42:12 AM MS  
Local: Nov 14, 2025 at 9:42:12 AM MS  
+37.290562,-104.82135  
Las Animas Count  
Altitude:2224.0mete  
Speed:0.0km/

**PHOTO 3: WEEDS OVERGROWN AROUND LOCATION. WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 506. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 4: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD. CUT AND REMOVE DEAD WEEDS PER RULE 606. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.**



Network: Nov 14, 2025 at 9:22:22 AM MS  
Local: Nov 14, 2025 at 9:22:22 AM MS  
+37.290844,-104.82145  
Las Animas Count  
Altitude:2223.9mete  
Speed:0.5km/

**PHOTO 5: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002., (2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 6: THE CA FOR OILY WASTE IN PRIME MOVER ENGINE SKID HAS BEEN ADDRESSED HOWEVER THESE ENGINE SKIDS SHOULD BE CLEANED AND MAINTAINED IN BETER CONDITIONS TO PREVENT STORMWATER FROM MIXING WITH OILY WASTE AND CAUSING RULE VIOLATIONS AFTER EVERY STORM EVENT.**



**PHOTO 7: ANCHOR MARKER IS DOWN ON THE NORTHEAST ANCHOR FROM WELLHEAD. Install proper guy line markers per Rule 1003.a. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.**