

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2025

Submitted Date:

11/14/2025

Document Number:

716301701

**FIELD INSPECTION FORM**

Loc ID 333417 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287035	WELL	SI	06/01/2025	CBM	071-09006	ULIBARRI 32-6 R	SI

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED		Date:
Type	WEEDS		
Comment:	PHOTO 3: WEEDS OVERGROWN AROUND LOCATION. PHOTO 4: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD.		
Corrective Action:	WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 606. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	PHOTO 6: THE CA FOR OILY WASTE IN PRIME MOVER ENGINE SKID HAS BEEN ADDRESSED HOWEVER THESE ENGINE SKIDS SHOULD BE CLEANED AND MAINTAINED IN BETER CONDITIONS TO PREVENT STORMWATER FROM MIXING WITH OILY WASTE AND CAUSING RULE VIOLATIONS AFTER EVERY STORM EVENT.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	PHOTO 7: ANCHOR MARKER IS DOWN ON THE NORTHEAST ANCHOR FROM WELLHEAD.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 287035 Type: WELL API Number: 071-09006 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/19/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 IS ON FILE

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSP. TO INSP. #716301186, THE CA FOR OILY WASTE IN SKID HAS BEEN ADDRESSED HOWEVER THE OTHER CA'S HAVE NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED.</p> <p>ECMC Inspection Report Summary                      On Tuesday 11-14-2025 at approximately 10:09, I Tom Beardslee                      Conducted an on-site inspection an Evergreen Natural Resources location ULIBARRI 32-6 R                      API# 05-071-09006 in Las Animas County Colorado.                      While there, I observed production operation.                      During this inspection the following possible compliance issues were observed:                      WEED MAINTENANCE, RULE 606, 2ND NOTICE IMMEDIATE ACTION REQUIRED.                      NO ANCHOR MARKER, RULERule 1003.a. 2ND NOTICE IMMEDIATE ACTION REQUIRED.                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	11/14/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404436999	INSPECTION SUBMITTED	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7331782">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7331782</a>
716301702	INSP. PHOTOS	<a href="https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7331690">https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7331690</a>