

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2025

Submitted Date:

11/25/2025

Document Number:

716301758

FIELD INSPECTION FORM

Loc ID 309440 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295029	WELL	PR	08/14/2008	CBM	071-09535	NEW ELK 25-04	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: PHOTO 4, 5, & 6: Impacted soil identified near compressor skid.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. this is the 2nd notice for this corrective action, immediate action is required.

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Compressor

1

Comment: FORM 4 SUNDRY IS ON FILE (VACUUM)

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Bradenhead	# 1	
Comment:	IS ACCESSABLE	
Corrective Action:		Date:
Type: Other	#	
Comment:	ABOVE GROUND 25 BBL PRODUCED WATER/ USED OIL TANK.	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 295029 Type: WELL API Number: 071-09535 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Comment: PHOTO 7: OILY WASTE IN COMPRESSOR SKID.						Date: <u>11/26/2025</u>
Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						
Permit:	Facility ID	Permit Num	Expiration Date			
	296580	2017101				

ECMC Comments		
Comment	User	Date
<p style="color: blue;">THIS IS A FOLLOW-UP TO INSP. DOC #698707773, CA HAS NOT BEEN ADDRESSED SATISFACTORILY NOT ALL IMPACTED SOIL WAS REMOVED AND LEAKING EQUIPMENT IS NOT FIXED.</p> <p style="color: blue;">ECMC Inspection Report Summary On Tuesday 11-25-2025 at approximately 13:14, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location NEW ELK 25-04 API# 05-071-09535 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: IMPACTED SOIL, RULE1002..(2).D. this is the 2nd notice for this corrective action, immediate action is required. OILY WASTE, RULE 1002..(2).D & 1002.f.(2)B, CA DATE 11-26-2025. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	11/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301759	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7349157