

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/01/2025

Document Number:

708907916

FIELD INSPECTION FORM

Loc ID: 324207 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264674	WELL	SI	07/01/2025	GW	045-08930	PUCKETT 41-36	SI

General Comment:

This is a Desktop Inspection/Audit of the scout card & related documents.

Inspected Facilities

Facility ID: 264674 Type: WELL API Number: 045-08930 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

Date: 12/31/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 12/01/2025 at approximately 12:56 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC PUCKETT 41-36 Location # 324207 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - Well lacks wellbore diagram - Comply with Rule 420 with a CA date of 12/31/2025</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of desktop inspection/audit report.</p>	smelserw	12/01/2025