

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29NENW

Location ID: 323861

Date: 11/25/2025



Location Overview – Photo #01735



Location – Photo #01736

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29NENW

Location ID: 323861

Date: 11/25/2025



Location – Photo #01740



Location – Photo #01738

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29NENW

Location ID: 323861

Date: 11/25/2025



No BMPs or Erosion Controls at Stream Crossing – Photo #01731



No BMPs or Erosion Controls at Stream Crossing – Photo #01732

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29NENW

Location ID: 323861

Date: 11/25/2025



Insufficient Erosion Controls on Lease Road – Photo #01744



Insufficient Erosion Controls on Lease Road – Photo #01745