

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404458482

Date Received:  
12/03/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

5 of 7 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<a href="mailto:ecmc.inspections@qb-energy.com">ecmc.inspections@qb-energy.com</a>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 718100978  
Inspection Date: 11/07/2025 FIR Submit Date: 11/14/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: QB ENERGY OPERATING LLC Company Number: 10844  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 335668

Location Name: N.PARACHUTE-65S96W Number: 26NESW County: \_\_\_\_\_  
Qtrqtr: NWSE Sec: 26 Twp: 5S Range: 96W Meridian: 6  
Latitude: 39.583280 Longitude: -108.136778

**FACILITY** - API Number: 05-045-00 Facility ID: 335668

Facility Name: N.PARACHUTE-65S96W Number: 26NESW  
Qtrqtr: NWSE Sec: 26 Twp: 5S Range: 96W Meridian: 6  
Latitude: 39.583280 Longitude: -108.136778

**CORRECTIVE ACTIONS:**

**1** CA# 209420

Corrective Action: Comply with Rule 603.o. Install or repair liner material to ensure spill or released materials will be maintained with containment structure. Date: 12/14/2025

Response: CA COMPLETED Date of Completion: 12/02/2025

Operator Comment: Repaired secondary containment liner to comply with ECMC rule 603.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 209421

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e, and clean up per Rule 912.a.

Date: 12/14/2025

Response: CA COMPLETED

Date of Completion: 12/02/2025

Operator Comment: Removed all trailered equipment and cleaned stained area to comply with Rule 608.e and 912.a.

ECMC Decision:

ECMC  
Representative:

**3** CA# 209422

Corrective Action: Remove and properly dispose fluids within containment.

Date: 12/04/2025

Response: CA COMPLETED

Date of Completion: 12/02/2025

Operator Comment: Pulled all fluids from containment for disposal and to ensure proper BMP.

ECMC Decision:

ECMC  
Representative:

**4** CA# 209423

Corrective Action: Conduct an evaluation of the BMP. Install or repair BMP as necessary to ensure any spill or released materials will be maintained with containment structure.

Date: 12/14/2025

Response: CA COMPLETED

Date of Completion: 12/02/2025

Operator Comment: Removed damaged containment and installed new BMP.

ECMC Decision:

ECMC  
Representative:

**6** CA# 209425

Corrective Action: Cover/Cap hose to prevent wildlife access pursuant to Rule 902.b, as well as to prevent spills.

Date: 11/21/2025

Response: CA COMPLETED

Date of Completion: 12/02/2025

Operator Comment: Installed cap on open ended hose to prevent wildlife access as well as spills.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: \_\_\_\_\_

Title: Compliance

Date: 12/3/2025 2:07:28 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404458482	FIR RESOLUTION SUBMITTED
404458516	New BMP
404458519	Repaired Liner
404458521	Capped Hose
404458523	Removed Trailer/Stain

Total Attach: 5 Files