

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2025

Submitted Date:

12/08/2025

Document Number:

708907988

FIELD INSPECTION FORM

Loc ID 324068 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
TEP		ECMCInspectionReports@flywheelenergy.com	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89068	WELL	PR	01/06/2000	GW	045-07398	AMERICAN SODA LLC GM 33-34	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 89068 Type: WELL API Number: 045-07398 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	Date: <u>01/07/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 12/08/2025 at approximately 11:19 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of TEP ROCKY MOUNTAIN LLC AMERICAN SODA LLC GM 33-34</p> <p>Location # 324068 in Garfield County Colorado.</p> <p>Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - Well lacks wellbore diagram - Comply with rule 420 with a CA date of 01/07/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of desktop inspection/audit report.</p>	smelserw	12/08/2025