




Looking at the former STATE #6 well. An open excavation is visible. Stockpiled soil is visible to the west of the former well. Orange construction fencing partially surrounds the excavation at the former well.



Frederick, CO, United States
Lat 40.100649, Long -104.954132
12/02/2025 14:37 GMT-07:00
ECMC : Environmental Inspection

46°F
 3.0 mph 5015.72 ft 3.84 m
 128° SE

Trash is visible on location.



Frederick, CO, United States
Lat 40.100562, Long -104.954189
12/02/2025 14:37 GMT-07:00
ECMC : Environmental Inspection


 

 46°F

 114° SE

 3.0 mph  5014.9 ft  7.2 m

Orange construction fencing partially surrounds an open excavation. Pieces of flowline are visible adjacent to the former well. A trench associated with Flowline Facility ID 478291 is visible running south from the former well.



Frederick, CO, United States

Lat 40.100504, Long -104.954247
12/02/2025 14:37 GMT-07:00
ECMC : Environmental Inspection



46° F


78° E

3.0 mph

5015.72 ft

7.96 m

Looking at the excavation. Slight gray staining is visible within the excavation; debris obscures visibility of the base of the excavation.



Frederick, CO, United States

Lat 40.100402, Long -104.954255
12/02/2025 14:38 GMT-07:00
ECMC : Environmental Inspection



46°F

282° W

3.0 mph

5018.34 ft

5.87 m

Looking at the excavation. Slight gray staining is visible within the excavation; debris obscures visibility of the base of the excavation.



Looking at the soil stockpile adjacent to the former well. No liner or stormwater BMPs are visible. Gray staining is visible in areas of the stockpiled soil.



Frederick, CO, United States

Lat 40.100505, Long -104.954277

12/02/2025 14:39 GMT-07:00

ECMC : Environmental Inspection



46°F

123° SE

3.0 mph


5012.07 ft

7.21 m

Looking at soil with gray staining in the stockpile. A petroleum hydrocarbon odor was observed when pieces of the stained soil were disturbed.



Looking at soil with gray staining in the stockpile. A petroleum hydrocarbon odor was observed when pieces of the stained soil were disturbed.



Frederick, CO, United States

Lat 40.100491, Long -104.954355

12/02/2025 14:40 GMT-07:00

ECMC : Environmental Inspection



46°F

75° E

3.0 mph

5015.26 ft

8.67 m