

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2025

Submitted Date:

12/11/2025

Document Number:

708908003

FIELD INSPECTION FORM

Loc ID 334087 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275966	WELL	PR	05/01/2023	GW	045-10412	BATTLEMENT MESA 35-12	PR
278676	WELL	PR	10/01/2024	GW	045-10919	BATTLEMENT MESA 35-32A	PR
285497	WELL	PR	05/01/2023	GW	045-12505	BATTLEMENT MESA 35-21D	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 275966 Type: WELL API Number: 045-10412 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420 Additionally the BATTLEMENT MESA 35-32A & BATTLEMENT MESA 35-21D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17	Date: <u>01/10/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278676 Type: WELL API Number: 045-10919 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285497 Type: WELL API Number: 045-12505 Status: PR Insp. Status: PR

Producing Well

Comment:	Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 12/11/2025 at approximately 14:40 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC BATTLEMENT MESA 35C-795 pad Location # 334087 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - BATTLEMENT MESA 35-12, BATTLEMENT MESA 35-32A & BATTLEMENT MESA 35-21D wells lack wellbore diagrams - Comply with Rule 420 with a CA date of 01/10/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of desktop inspection/audit report.</p>	smelserw	12/11/2025