

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2025

Submitted Date:

12/05/2025

Document Number:

716301774

FIELD INSPECTION FORM

Loc ID 307443 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217670	WELL	TA	02/13/2014	GW	071-06449	LAURIE 24-14	TA

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run

1

corrective date

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

0

Comment: Bradenhead inaccessible or not visible.

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date: 12/19/2025

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217670 Type: WELL API Number: 071-06449 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT PERFORMED ON 5/15/2023

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/07/2009 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 IS ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 257249 Lat: 37.164003 Long: -104.757996

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW-UP TO INSP. DOC#716300076, CA HAS BEEN ADDRESSED HOWEVER THERE IS A NEW CORRECTIVE ACTION. ECMC Inspection Report Summary On Tuesday 12-5-2025 at approximately 11:22, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location LAURIE 24-14 API# 05-071-06449 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: NO BRHD ACCESS, Rule 419.a.(1), (2), CA DATE 12-19-2025 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.	beardslt	12/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404462637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362889
716301775	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362886