

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2025

Submitted Date:

12/05/2025

Document Number:

718000055

FIELD INSPECTION FORM

Loc ID: 421034 Inspector Name: ALLISON, RICK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ECMC Enforcement		dnr_ecmc_enforcement@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Jeff White		jeffery.white@chevron.com	
Graber, Nikki		nikki.graber@state.co.us	
, Inspections		rbucogccinspectionreports@chevron.onmicrosoft.com	All Chevron Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490714	SPILL OR RELEASE	AC	06/19/2025		-	Spaur USX AB 33-07	EI

General Comment:

Inspected Facilities

Facility ID: 490714 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Operator reported Spill ID 490714 discovered 6/16/2025 "Final laboratory analytical results received on 6/16/2025 indicate that soil sample SEP01-FL@4', discovered at the separator riser, exceeded ECMC Table915 standards for 1-Methyl – Naphthalene (0.0615 mg/kg) and 2-Methyl- Naphthalene (0.0266 mg/kg)."

Remediation Project 33999 was opened for site investigation during decommissioning.

As of 12/5/2025 no Supplemental Spill Reports or Supplemental Form 27 Site Investigation and Remediation Workplans have been received documenting the investigation and cleanup of the reported Release since the Initial Form 19 was submitted on 6/17/2025.

Rule 912.a.(2) and Rule 913.d.(1) requires that Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Rule 912.b. requires Operators to obtain closure of a Spill/Release within 90 days of the Spill/Release discovery. Rule 913.e. requires quarterly update reports in a Supplemental Form 27 to document progress of site investigation and Remediation. Operator is overdue on reports and out of compliance with the cited Rules.

Corrective Action:	Comply with Rules 912.a.(1), 913.d.(1), 912.b., 913.e.	Date: _____
	Submit Supplemental Form 27 with all data collected to date and a plan and schedule for remediation of the Release. Submit a Supplemental Form 19 for Spill/Release closure concurrent with submitted the Supplemental Form 27.	

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404462537	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362671
718000056	SpaurUSXAB33-07TANK-photos12-5-2027	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7362661