

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2025

Submitted Date:

12/08/2025

Document Number:

716301792

FIELD INSPECTION FORM

Loc ID 308577 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
B WARD, GIENA		gward@ogrisop.com	All Inspections
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274791	WELL	PR	12/07/2007	GW	071-08254	HILL RANCH 36-10	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: IMPACTED SOIL BETWEEN PRIME MOVER AND WELLHEAD.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.	Date:	12/15/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 274791 Type: WELL API Number: 071-08254 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

PHOTO 5: No pit permit on file for existing pit.

Corrective Action

Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.a.

Date: 01/08/2026

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 12-8-2025 at approximately 13:27, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location HILL RANCH 36 -10 API# 05-071-08254 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: IMPACTED SOIL, RULE 1002,.(2).D. CA DATE 12-15-2025. NO PIT PERMIT, rule 908.a. CA DATE 1-8-2026. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	12/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404464486	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365424
716301793	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7365419