
Re: Burlington Northern 1 (05-005-06772) Re-Entry

From Jacobson - DNR, Eric <eric.jacobson@state.co.us>

Date Thu 10/23/2025 3:00 PM

To Trey Sloan <tsloan@civiresources.com>

Cc Matt Thome <mthome@civiresources.com>; TJ Hanneman <thanneman@civiresources.com>; Regulatory <regulatory@civiresources.com>; Randy Williams <rwilliams@civiresources.com>; Dave Magruder <dmagruder@civiresources.com>

Trey

Approved as outlined. Please include the casing and cement details on the Form 6 SROA.

Thanks Eric

On Thu, Oct 23, 2025 at 1:54 PM Trey Sloan <tsloan@civiresources.com> wrote:

Eric,

Just wanted to give you a heads up that during re-entry operations on the Burlington Northern 1 (05-005-06772) we pressure tested the existing surface casing and it failed with multiple holes so we are cementing a 7" casing string inside the surface for isolation. Please let me know if you have any issues.

Thanks,

Trey Sloan

Production Engineer

Cell: 918-534-6637

555 17th Street | Suite 3600 | Denver, CO | 80202

www.civitasresources.com | NYSE: CIVI



--

Eric Jacobson
Engineer



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

P 303-548-7396

1120 Lincoln Street, Suite 801, Denver, CO 80203

eric.jacobson@state.co.us | www.colorado.gov/ecmc