

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404474547

Date Received:
12/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

MACH EH&S

ehsinspections@machnr.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300850

Inspection Date: 10/22/2025

FIR Submit Date: 10/24/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306768

Location Name: HOTTER GAS UNIT A-M34N9W Number: 17NESW County: LA PLATA

Qtrqr: NESW Sec: 17 Twp: 34N Range: 9W Meridian: M

Latitude: 37.190874 Longitude: -107.851403

FACILITY - API Number: 05-067-00 Facility ID: 263683

Facility Name: HOTTER A Number: 2

Qtrqr: NESW Sec: 17 Twp: 34N Range: 9W Meridian: M

Latitude: 37.190874 Longitude: -107.851403

CORRECTIVE ACTIONS:

1 CA# 208922

Corrective Action: Maintian adequate freeboard to prevent mixing of produced fluids and precipitation. Note: any evidence that fluids contain wastes such as color or rainbow sheen should be treated and disposed of properly according to type of waste.

Date: 10/31/2025

Response: CA COMPLETED

Date of Completion: 11/20/2025

Operator Comment: Contents from BGT removed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 208923

Corrective Action: Install/repair sign

Date: 11/24/2025

Response: CA COMPLETED

Date of Completion: 12/12/2025

Operator
Comment: New sign made and installed.

ECMC Decision: _____

ECMC
Representative:

3 CA# 208924

Corrective Action: maintain freeboard/containment volume, fluid within inches from overflowing. Fluid is slightly discolored and may contain chemical product or residues and shall be treated and dsiposed appropriately for type of waste.

Date: 10/31/2025

Note: freezing of fluid may also cause damage to full container due to expansion

Response: CA COMPLETED

Date of Completion: 11/20/2025

Operator
Comment: Fluid removed.

ECMC Decision: _____

ECMC
Representative:

4 CA# 208925

Corrective Action: Clean up material per rule 1002.f and 907 and dispose in approved manner appropriate for type of waste. Maintain/modify equipment to prevent any additional releases/recurrence of conditions.

Date: 11/24/2025

Response: CA COMPLETED

Date of Completion: 11/20/2025

Operator
Comment: Stained soil removed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CAs complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca

Signed: _____

Title: Regulatory/Compliance

Date: 12/19/2025 2:07:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404474547	FIR RESOLUTION SUBMITTED
404474655	CA Photo (Sign)
404481242	Containment Fluid Removed
404481244	BGT Fluid Removed
404481253	Hotter A2 Soil Clean Up
404481256	BGT Contents Pulled

Total Attach: 6 Files