

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2026

Submitted Date:

01/05/2026

Document Number:

716301910

FIELD INSPECTION FORM

Loc ID 307351 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217526	WELL	PR	02/01/2004	CBM	071-06303	G.K.S. 33-29	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 5: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE, 10 DAYS TO REMOVE IMPACTED SOILS. 1/16/2026.

Corrective Action:

REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE 1/6/2026, 10 DAYS TO REMOVE IMPACTED SOILS. 1/16/2026.

Date: 01/16/2026

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

5

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 217526 Type: WELL API Number: 071-06303 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/25/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On 1/5/2026 at approximately 13:15, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location G.K.S 33-29, API# 05-071 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 5: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE 1/6/2026, 10 DAYS TO REMOVE IMPACTED SOILS. 1/16/2026.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	01/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301911	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401758