



00247727

**OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**

*W*  
JAN 19 1996

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 075 - <del>28715</del>		LEASE NAME: <i>Budin 15</i>	
LOCATION: <i>SESE 2-8N-55W</i>		OPERATOR: <i>Barenenergy</i>	
DATE: <i>1-11-96</i>		INSPECTOR: <i>Bill O'Leary</i>	
Insp. Type: <i>SP</i>	Insp. Status: <i>PA</i>	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/>
		Viol.: Y <input type="radio"/> N <input checked="" type="radio"/>	NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	<i>Well plugged site revealed.</i>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)	<i>2-500 bolted, pipe, tank shed</i>	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	<i>grassland</i>	
<b>Miscellaneous</b>	<i>Dead calf found tangled in junk left near site.</i>	

**CORRECTIVE ACTION REQUIRED:** *Comply with rule 317 a.8.*

Date Corrective Action Required By: *2-15-96* Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

*Notify landowner regarding dead calf.*



Suite 3900, 1801 California Street, Denver, CO 80202 (303) 295-2323  
Mailing Address: P. O. Box 5850, Denver, CO 80217 Fax: (303) 297-3752



January 30, 1996

Colorado Oil & Gas  
Conservation Commission  
1120 Lincoln Street, Suite 801  
Denver, CO 80203

Re: Field Inspection Report  
Budin Lease  
Logan County, CO

Gentlemen:

On January 11, 1996, Mr. Ed Binkley, Field Inspector for the Commission, inspected the wells on the subject lease which all have been abandoned. Well No. 1 received a satisfactory inspection, however, Well Nos. 2, 3, 8 and 15 all received notices of unsatisfactory inspection. The corrective action required for all of these wells was to comply with Rule 317A.8 which requires the removal of all equipment and junk from locations which have been abandoned, or the securing of the landowner's written permission to leave any equipment on the locations.

Attached, please find a letter dated January 24, 1996, from Mr. Rudy Budin surface owner of the Budin Lease. In this letter, Mr. Budin has indicated that he has purchased the remaining 500 bbl tanks at the old tank battery site for his personal use and wishes for them to remain in the present position. He has also stated that Berenergy Corporation may store additional equipment as necessary near the old tank battery facility and that he is satisfied with the surface restoration on the above wells. Based on the attached letter, Berenergy Corporation has fulfilled the requirements of Rule 317A.8 for the Budin Nos. 2, 3, 8 and 15. In addition, it was noted on the Budin No. 15 wellsite that a dead calf was found near some junk left at the site. The landowner, Mr. Rudy Budin was already aware of this dead calf and had indicated to Berenergy Corporation that it was his responsibility and that we should leave it in its present position.

All corrective action required by the above Field Inspection Reports have been fulfilled by Berenergy Corporation as of this date.

Sincerely,

J. Roy White  
Operations Manager

JRW:ppq

JAN 31 1996

RECEIVED JAN 29 1996

January 24, 1996

Mr. J. Roy White  
Operations Manager  
BERENERGY CORPORATION  
1801 California Street, Suite 3900  
Denver, CO 80202

Re: Budin Lease  
Logan County, Colorado

Dear Mr. White:

Berenergy Corporation has plugged and abandoned all producing wells on the Budin Lease. The 2-500 bbl tanks remaining at the old tank battery site have been purchased for my personal use and are no longer the property of Berenergy Corporation.

Permission is also granted for Berenergy Corporation to store additional equipment as necessary near the old tank battery facility until use of the equipment is required at another location.

The surface restoration of both the old tank battery facility and all wells which have been plugged and abandoned has been completed to my satisfaction, therefore, no additional work is required for the restoration of the surface on the Budin Lease.

Sincerely,



Rudy Budin  
4731 County Road 38  
Sterling, CO 80751

5-4-79

Called Linda Niebar  
for Status