

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

RECEIVED

JAN 16 1968



le in duplicate for Patented and Federal lands. le in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [ ] OTHER [ ]
2. NAME OF OPERATOR PAT'S POWER TONGS, INC.
3. ADDRESS OF OPERATOR Box 702, Grand Junction, Colorado 81501
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 3299' FSL, 1948' FWL At proposed prod. zone C - E/2 Lot 9, Sec. 5
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4396' K.B.
7. UNIT AGREEMENT NAME Liberty "J" Sand
8. FARM OR LEASE NAME MALLO
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Liberty [check]
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S.5, T.8N., R.54W.
12. COUNTY OR PARISH Logan [check] 13. STATE Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [ ] PULL OR ALTER CASING [ ] WATER SHUT-OFF [ ] REPAIRING WELL [ ]
FRACTURE TREAT [ ] MULTIPLE COMPLETE [ ] FRACTURE TREATMENT [ ] ALTERING CASING [ ]
SHOOT OR ACIDIZE [ ] ABANDON [X] SHOOTING OR ACIDIZING [ ] ABANDONMENT [ ]
REPAIR WELL [ ] CHANGE PLANS [ ] (Other) [ ]
(Other) [ ] (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well is now known as LU-5 and has been purchased by the above designated company for salvage. It will be plugged and abandoned as follows:

Spot 15 sack plug in the 5 1/2" casing from 5268' to 5398' covering the perfs 5332 - 40. Bradenhead squeeze.

Shoot off 5 1/2" casing.

Fill hole with heavy mud and spot 10 sx. plug from 195' to 225' depth over base of 9-5/8" @ 212' depth.

Spot 5 sack plug in top of surface to bottom of cellar.

Weld on steel plate to top of surface casing at base of cellar.

Fill cellar with earth, rock and top off with top soil.

Table with 2 columns and 5 rows: DVR, FJP, HHM, JAM, JJD. Checkmarks are present in the second column for FJP, HHM, JAM, and JJD.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent/Pat's Power Tongs DATE 1-15-68

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Director DATE JAN 16 1968

CONDITIONS OF APPROVAL, IF ANY:

COLO. OIL & GAS CONS. COMM.