

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404500617

Date Received:  
01/09/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LLC  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Blair, Jamie</u>		<u>jamie.blair@state.co.us</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>General</u>		<u>CO2Source_Regulatory@kindermorgan.com</u>
<u>Roy, Catherine</u>		<u>catherine.roy@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 721100042  
Inspection Date: 01/02/2026 FIR Submit Date: 01/07/2026 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: KINDER MORGAN CO2 CO LLC Company Number: 46685  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**LOCATION** - Location ID: 454942

Location Name: DC Number: 22 Pad County: DOLORES  
Qtrqr: SESW Sec: 8 Twp: 40N Range: 17W Meridian: N  
Latitude: 37.737200 Longitude: -108.751610

**FACILITY** - API Number: 05-033-00 Facility ID: 454941

Facility Name: DC Number: 22  
Qtrqr: SESW Sec: 8 Twp: 40N Range: 17W Meridian: N  
Latitude: 37.737200 Longitude: -108.751610

**CORRECTIVE ACTIONS:**

**1** CA# 210317

Corrective Action: Comply with 1003 or confirm anchors not present. Date: 01/09/2026

Response: CA COMPLETED Date of Completion: 01/09/2026

Verified that no rig anchors are present on the DC-22 CO2 production well location. The well was drilled with a

Operator Comment: Precision super single rig that required no anchors to be installed for guy wires. The rig used for well completion utilized a base beam for support, no need for anchors.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: After a telephone conversation with Southwest Compliance Supervisor Steve Labowskie, this FIRR is being submitted to resolve a corrective action that was erroneously included on a recent Field Inspection Report (Doc #721100042).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Hannigan

Signed: \_\_\_\_\_

Title: EHS Supervisor

Date: 1/9/2026 10:59:43 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

404500617	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files