

Date of Inspection	12/30/2025
Inspector Name	Tyson Dilka, Stelbar
Location Name	Price 9
API	05-121-10437
COGCC Loc ID	317293
County	Washington
Location Directions	CR 22 & TT, E 2.5, N into
Lat/Long	39.896777, -102.8893
TB Inspected	Former well & tank battery
Equipment on Site	No
Livestock Grazing	Yes
Fences	No
Weeds or Debris	No
Visual of Vegetative Cover	Location is visually observed at 80% overall
Stormwater	No stormwater issues observed, cattle and burrowing animals have created minor disturbance
Recommendations	Final Reclamation Release
Photos	See below 1-6
Response to Inspection	<p>The access roads east and west and the meter house disturbance west of the Price 9 location do not require reclamation by Stelbar, as it serves as access for the High Plains Gathering System. This HP Gathering operating interest was transferred to Smith Energy in 2018, after the Price 9 well was plugged and abandoned in 2017. Please reference photo 1 below and attached transfer agreements referencing T2S-R49W-S8.</p> <p>Photo 6 in document 708201894 indicates bare soil at the former separator location. This area was dormant seeded prior to the inspection by ECMC in Jan 2025 and now shows progression towards reclamation standards from the 2025 growing season. Please reference photo 2 below.</p>




Photo 1. Map showing Smith Energy and High Plains Gathering access and disturbance.



Photo 2. Photo from SW side of location facing NW showing progression of vegetation establishment at former separator location.



Photo 3. Middle of location facing N.



Photo 4. Middle of location facing E.



Photo 5. Middle of location facing S.



Photo 6. Middle of location facing W.