

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404510482

Date Received:
01/19/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dolezal, Pat</u>	<u>970-332-3585</u>	<u>pat.dolezal@ownresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 720900518
Inspection Date: 01/07/2026 FIR Submit Date: 01/11/2026 FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC Company Number: 10699
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 304849

Location Name: WILLIAMS-61N45W Number: 21SESW County: YUMA
Qtrqtr: SESW Sec: 21 Twp: 1N Range: 45W Meridian: 6
Latitude: 40.033930 Longitude: -102.409710

FACILITY - API Number: 05-125-00 Facility ID: 275549

Facility Name: WILLIAMS Number: 24-21
Qtrqtr: SESW Sec: 21 Twp: 1N Range: 45W Meridian: 6
Latitude: 40.033930 Longitude: -102.409710

CORRECTIVE ACTIONS:

1 CA# 210373

Corrective Action: Comply with Rule 609.a. Date: 01/20/2026

Response: CA COMPLETED Date of Completion: 01/13/2026

Operator Comment: Saturated soil was removed from location and disposed by Bohler Well Service at Pawnee Waste in Grover Colorado, Redediatin project # 40141

ECMC Decision: _____

ECMC
Representative:

2 CA# 210374

Corrective Action: Comply with Rule 602.c.

Date: 01/12/2026

Response: CA COMPLETED

Date of Completion: 01/12/2026

Operator Comment: Tank was removed from location, Remediation project # 40141

ECMC Decision:

ECMC
Representative:

3 CA# 210375

Corrective Action: Comply with Rule 606.

Date: 01/19/2026

Response: CA COMPLETED

Date of Completion: 01/12/2026

Operator Comment: Tank was removed and debris removed from location, remediation project # 40141

ECMC Decision:

ECMC
Representative:

4 CA# 210376

Corrective Action: Comply with Rule 609.a.

Date: 01/27/2026

Response: CA COMPLETED

Date of Completion: 01/09/2026

Operator Comment: Risers were removed from location per Remediation project #40141

ECMC Decision:

ECMC
Representative:

5 CA# 210377

Corrective Action: Install sign to comply with Rule 605.e.

Date: 02/11/2026

Response: CA COMPLETED

Date of Completion: 01/12/2026

Operator Comment: Tank has been removed from location, no sign needed, remediation project #40141

ECMC Decision:

ECMC
Representative:

6 CA# 210378

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 01/14/2026

Response: CA COMPLETED

Date of Completion: 01/13/2026

Operator Comment: Saturated soil was removed from location and disposed by Bohler Well Service at Pawnee Waste in Grover Colorado, remediation project #40141

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: _____

Title: Regulatory Specialit

Date: 1/19/2026 10:16:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

404510482	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files