

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/19/2026

Submitted Date:

01/19/2026

Document Number:

719001103

FIELD INSPECTION FORM

Loc ID 326525 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

General Comment:

[Inspection Report Summary](#)
On 1/19/26 | Inspector Charles Garcia conducted an desktop follow up inspection. Location: ARGENTA34-10 34-1 API# 067-08245 Operator: HILLCORP ENERGY COMPANY County: LaPlata SHARED LOCATION WITH ARGENTA 34-10 34-1A DOC #719000760 FIR #404487010 SEE ATTCHED PICTURES DOC#404487013 CA DEEP RUTS ACROSS LOCATION PER RULE 1002.f and "maintain facility", CA HAS BEEN RESSOLVED

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: DEEP RUTS ACROSS LOCATION SEE LOCATION PICTURES
 CA PER RULE 1002.f and "maintain facility",
 CA RESOVED

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
CA DEEP RUTS ACROSS LOCATION PER RULE 1002.f and "maintain facility", CA RESOVED	garciacr1	01/19/2026