

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:  
 404475459  
 Date Received:  
 12/17/2025

ECMC Operator Number: 10633 Contact Name: Trey Sloan  
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 2939100  
 Address: 555 17TH STREET SUITE 3700 Fax: \_\_\_\_\_  
 City: DENVER State: CO Zip: 80202 Email: tsloan@civiresources.com

**For "Intent" 24 hour notice required,** Name: Medina, Justin Tel: (720) 471-0006  
 Email: justin.medina@state.co.us  
**ECMC contact:**

Type of Well Abandonment Report:  Notice of Intent to Abandon  Subsequent Report of Abandonment

API Number 05-005-06571-00  
 Well Name: STATE OF COLO 'V' Well Number: 3  
 Location: QtrQtr: SWNW Section: 19 Township: 5S Range: 64W Meridian: 6  
 County: ARAPAHOE Federal, Indian or State Lease Number: 70/8009S  
 Field Name: LOWRY Field Number: 52075

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 39.603775 Longitude: -104.601800  
 GPS Data: GPS Quality Value: \_\_\_\_\_ Type of GPS Quality Value: PDOP Date of Measurement: \_\_\_\_\_  
 Reason for Abandonment:  Dry  Production Sub-economic  Mechanical Problems  
 Other Re-enter to Re-plug  
 Casing to be pulled:  Yes  No Estimated Depth: \_\_\_\_\_  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	8542	8582	11/14/1972	CEMENT	8385
Total: 1 zone(s)					

**Casing History**

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	NA	24	0	267	200	267	0	VISU
1ST	7+7/8	5+1/2	NA	15.50	0	8644	550	8644	6250	VISU
S.C. 1.1	7+7/8	5+1/2	NA	15.5		2080	400	2080	325	

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7680 with 4 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>30</u>	sks cmt from <u>3150</u>	ft. to <u>2900</u>	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>35</u>	sks cmt from <u>2240</u>	ft. to <u>1980</u>	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>180</u>	sks cmt from <u>1900</u>	ft. to <u>350</u>	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at <u>3000</u>	ft. with <u>50</u>	sacks. Leave at least 100 ft. in casing	<u>3150</u>	CICR Depth
Perforate and squeeze at <u>2290</u>	ft. with <u>45</u>	sacks. Leave at least 100 ft. in casing	<u>2240</u>	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth
Perforate and squeeze at _____	ft. with _____	sacks. Leave at least 100 ft. in casing	_____	CICR Depth

(Cast Iron Cement Retainer Depth)

Set 115 sacks half in. half out surface casing from 320 ft. to 0 ft. Plug Tagged:   
 Set 10 sacks at surface  
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
 Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing  
 Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_ Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105  Yes  No

Technical Detail/Comments:

Attachments:

- Proposed WBD
- Surface owner consent
- Location Photos of staked wellhead

No CPW consultation required for typical work associated with P&A in this type of big game HPH.  
 Unable to confirm casing grade with historical documentation (used NA).  
 Operator will use secondary containment for all tanks and other liquid containment.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Mandie Flinn  
 Title: Engineering Tech Date: 12/17/2025 Email: dlabandonment@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved, Eric

ECMC Approved:

Date: 1/20/2026

**CONDITIONS OF APPROVAL, IF ANY LIST**

Expiration Date: 7/19/2026

<b><u>COA Type</u></b>	<b><u>Description</u></b>
	Operator shall implement measures to control venting, to protect health and safety, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public welfare.
	Due to proximity to a mapped wetland, operator will implement stormwater BMPs and erosion control measures as needed to prevent sediment and stormwater runoff from entering the wetland.
	COA's provided by the operator as Best Management Practices under Technical Detail / Comments: Operator will use secondary containment for all tanks and other liquid containment.
	CBL to be run prior to plugging to verify stage tool setting depth and existing coverage - submit to ECMC for verification of plugging orders prior to continuing plugging operations.
	1) Provide electronic Form 42 Notice of MIRU 2 business days ahead of operations and electronic Form 42 Notice of Plugging Operations 48 hours prior to mobilizing for plugging operations. These are two separate notifications, required by Rules 405.e and 405.i. 2) Pump surface casing shoe plug at 320' only after isolation has been verified. If surface casing cement is not circulated to surface, shut-in, WOC 4 hours then tag plug – must be at 217' or shallower and provide a minimum of 10 sx plug at the surface. 3) Leave at least 100' of cement in the wellbore for each plug without mechanical isolation. 4) After cut and prior to cap, verify isolation by either a 15 minute bubble test or 15 minute optical gas imaging recording. If there is indication of flow contact ECMC Engineering. Provide a statement on the 6SRA which method was used and what was observed. Retain records of final isolation test for 5 years. 5) With the Form 6 SRA operator must provide written documentation which positively affirms each COA listed above has been addressed.
	"As-Drilled" well location GPS data has not been reported for this well. Operator will obtain the GPS data pursuant to Rule 216 and submit it on the Form 6 Subsequent Report of Abandonment.

6 COAs

**ATTACHMENT LIST**

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
404475459	FORM 6 INTENT SUBMITTED
404478194	SURFACE OWNER CONSENT
404478198	LOCATION PHOTO
404478236	WELLBORE DIAGRAM

Total Attach: 4 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
OGLA	Location Assessment review complete.	01/19/2026
OGLA	Location is in a CPW mapped Pronghorn Winter Concentration Area High Priority Habitat. Although plugging and abandonment operations with heavy equipment will be allowed, the operator is strongly encouraged to avoid them from January 1 through April 30.	01/19/2026
Engineer	Deepest Water Well within 1 Mile – 1672' SB5 Base of Fox Hills - 2189' SB5 Base of Upper Arapahoe - 1642' SB5 Base of Denver - 1058' SB5 Base of Lower Dawson - 299'  Lower Dawson / 5696 / 5801 / 46.3 / 299 / 194 / 14.82 / NNT Denver / 4937 / 5674 / 284.6 / 1058 / 321 / 77.41 / NNT Upper Arapahoe / 4353 / 4841 / 235.2 / 1642 / 1154 / 63.97 / NT Laramie-Fox Hills / 3806 / 4024 / 153.5 / 2189 / 1971 / 36.84 / NT	12/23/2025
Permit	Permitting Review Complete • Verified completed interval (Doc 428812). • No production reporting to verify; well produced before ECMC database began.	12/18/2025

Total: 4 comment(s)