

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404520312

Date Received:
01/27/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>. General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 719001174
Inspection Date: 01/21/2026 FIR Submit Date: 01/22/2026 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326205

Location Name: HUBER/SPC-FEDERAL-N35N8W Number: 24NWNW County: LA PLATA
Qtrqr: NWN Sec: 24 Twp: 35N Range: 8W Meridian: N
W
Latitude: 37.292990 Longitude: -107.702050

FACILITY - API Number: 05-067-00 Facility ID: 216040

Facility Name: HUBER/SPC-FEDERAL Number: 1-24
Qtrqr: NWN Sec: 24 Twp: 35N Range: 8W Meridian: N
W
Latitude: 37.292990 Longitude: -107.702050

CORRECTIVE ACTIONS:

1 CA# 210563

Corrective Action: "Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used" Date: 01/25/2026

Response: CA COMPLETED Date of Completion: 01/23/2026

Lube oil containment has been emptied.

Operator Comment: _____

ECMC Decision: _____

ECMC Representative: _____

2 CA# 210564

Corrective Action: MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND ENGINE SKID rule 1002.f

Date: 01/29/2026

Response: CA COMPLETED

Date of Completion: 01/27/2026

Operator Comment: Cleaned up impacted soil and replaced with clean fill

ECMC Decision: _____

ECMC Representative: _____

3 CA# 210565

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/29/2026

Response: CA COMPLETED

Date of Completion: 01/27/2026

Operator Comment: Dug culvert out to restore functionality

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Resolved - see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 1/27/2026 10:54:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404520312	FIR RESOLUTION SUBMITTED
404520324	Resolve Photos

Total Attach: 2 Files