

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/21/2026

Document Number:

699507779

FIELD INSPECTION FORM

Loc ID 320156 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Findings:

- 11 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Triesch, Autumn		autumn.triesch@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202852	WELL	SI	07/01/2017	OW	001-08257	THOMPSON-PRICE 2	SI

General Comment:

Request inspection for Autumn Triesch. Equipment had not changed since previous audit.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Unable to identify wellhead sign due to weed growth		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: <u>02/21/2026</u>
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	weeds unmanaged on location		
Corrective Action:	Comply with rule 606		Date: <u>02/21/2026</u>
Type	OTHER		
Comment:	Annual bradenhead test is not current.		
Corrective Action:	Comply with rule rule 606.		Date: <u>02/21/2026</u>
Type	OTHER		
Comment:	water tank has overflowed on location and caused spill		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>02/21/2026</u>
Type	OTHER		
Comment:	According to COGCC data this well has been shut in since 7/1/17. Missing production data from 8/1/19 to present. This well has been shut in for more than 2 years and is in need of a MIT according to MIT rules.		
Corrective Action:	Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.		Date: <u>02/21/2026</u>
Type	OTHER		
Comment:	weeds on lease road unmanaged		
Corrective Action:	Repair and maintain lease road to comply with rule 204.		Date: <u>02/21/2026</u>
Type	OTHER		
Comment:	Berms inadequate on location		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.		Date: <u>02/21/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202852 Type: WELL API Number: 001-08257 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/31/2019 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: TSTM

Comment: In need of bradenhead test

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On 1/15/21 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Thompson price 2 Company Name- In process of transfer API- 05-001-08257 In Adams county Colorado. While there, I observed SI well. This is a follow up inspection from document # 699503341, Audit request from Autumn Triesch, Enforcement Advisor. During this inspection the following possible compliance issues were observed: Wellhead sign. Rule 605d. 2/21/26 Weeds. Rule 606. 2/21/26 MIT. Rule 417. 2/21/26 Bradenhead test. Rule 606. 2/21/26 Berms. Rule 603.o. 2/21/26 Spill. Rule 912 a. 2/21/26 Access. Rule 204. 2/21/26 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	01/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404514008	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7422387
699507780	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7422385