

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404522785

Date Received:
01/28/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
QB ENERGY		ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708908316
Inspection Date: 01/20/2026 FIR Submit Date: 01/20/2026 FIR Status:

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335857

Location Name: 697-13C-66S97W Number: 13SESW County:
Qtrqr: SESW Sec: 13 Twp: 6S Range: 97W Meridian: 6
Latitude: 39.518910 Longitude: -108.172760

FACILITY - API Number: 05-045- -00 Facility ID: 335857

Facility Name: 697-13C-66S97W Number: 13SESW
Qtrqr: SESW Sec: 13 Twp: 6S Range: 97W Meridian: 6
Latitude: 39.518910 Longitude: -108.172760

CORRECTIVE ACTIONS:

1 CA# 210484

Corrective Action: Comply with CECMC Rules 602 & 608 Date: 01/27/2026

Response: CA COMPLETED Date of Completion: 01/28/2026

Operator Comment: Replaced plug on choke body to comply with rule 602 & 608

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nick Croy

Signed: _____

Title: Compliance

Date: 1/28/2026 2:21:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404522785	FIR RESOLUTION SUBMITTED
404522791	Replaced plug on choke body to comply with rule 602 & 608

Total Attach: 2 Files