

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/22/2026

Document Number:

719001174

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GARCIA, CHARLES On-Site Inspection
 326205 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
 Name of Operator: HILCORP ENERGY COMPANY
 Address: P O BOX 61229
 City: HOUSTON State: TX Zip: 77208

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216040	WELL	PR	03/28/2000	CBM	067-07646	HUBER/SPC-FEDERAL 1-24	DM

General Comment:

Inspection Report Summary
 On 1/22/26 | Inspector Charles Garcia conducted an on-site inspection.
 Location: HUBER/SPC-FEDERAL 1-24
 API# 067-07646
 Operator: HILLCORP ENERGY COMPANY
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	3 UNMARKED SEE LOCATION PICTURES		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION IN COMPLIANCE		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	LUBE OIL CONTAINER WITH SPILL PREVENTION FOR PRIME MOVER APPROXIMATELY 3 IN FROM TOP SEE LOCATION PICTURES		
Corrective Action:	"Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used"		Date: <u>01/25/2026</u>
Type: Prime Mover	# 1		
Comment:	GAS ENGINE FOR PRIME MOVER LEAKING OIL BOTH SIDES OF ENGINE SKID SATURATED WITH OIL SEE LOCATION PICTURES		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND ENGINE SKID rule 1002.f		Date: <u>01/29/2026</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Culverts	Fail					

Comment: **CULVERT AT LOCATION ENTERANCE FILLED WITH SEDIMENT AND NOT FUNCTIONING PROPERLY SEE LOCATION PICTURES**

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 01/29/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404516428	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424747
719001182	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424743