

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404529695

Date Received:  
02/03/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		FarmingtonRegulatoryTechs@hilcorp.com
Labowskie, Steve		steve.labowskie@state.co.us
Blair, Jamie		jamie.blair@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100092  
Inspection Date: 01/27/2026 FIR Submit Date: 01/30/2026 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326292

Location Name: HUBER-NELSON-N35N8W Number: 31NENW County: LA PLATA  
Qtrqtr: NENW Sec: 31 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.262540 Longitude: -107.789750

FACILITY - API Number: 05-067-00 Facility ID: 216183

Facility Name: HUBER-NELSON Number: 2-31  
Qtrqtr: NENW Sec: 31 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.262540 Longitude: -107.789750

CORRECTIVE ACTIONS:

1 CA# 210712

Corrective Action: Securely fasten all valves, pipes, fittings, and production facilities to ensure good mechanical condition, For all hydraulic-drive system pumps, drives, reservoirs and hoses:  
1. Inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.  
2. Remove contaminated gravel and properly dispose to comply with 1002.f

Date: 02/03/2026

Response: CA COMPLETED

Date of Completion: 02/02/2026

Operator Comment: Inspection at regular intervals will continue and repairs have been made. Removed contaminated soil has been removed and replaced with clean fill. Numerous other items referenced in the inspection have been addressed (shown in photos)

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech Date: 2/3/2026 5:44:32 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404529695	FIR RESOLUTION SUBMITTED
404529696	HUBER-NELSON 2-31_721100092_Resolved Photos

Total Attach: 2 Files