




**peterson energy  
management, inc.**



00261353



Well File  
NESW 16-10N-47



April 30, 1997

Ed Binkley  
Colorado Oil & Gas Conservation Comm.  
1120 Lincoln #801  
Denver, CO 80203

RE: API No: 05-115-06053  
Lease Name: State 16-11-1

Dear Ed:

We have taken the corrective action required per your field inspection report dated February 13, 1997. Attached please find the statement from DC Dozer Service dated April 23, 1997, which indicates that work was performed 3/28, 4/19, and 4/20.

Sincerely,

Andy Peterson  
President

**petroleum engineering**

# COLORADO OIL & GAS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- <u>115 - 06053</u>	LEASE NAME: <u>State 16-11-1</u>
LOCATION: <u>NE5W 16-10N-47W</u>	OPERATOR: <u>Peterson Energy Inc</u>
DATE: <u>2-13-97</u>	INSPECTOR: <u>Ed Burkley</u>
Insp. Type: <u>SR</u> Insp. Status: <u>DA</u> PA: <u>Y I N</u>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input type="radio"/> N <input checked="" type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<u>no grass, level -</u>	
<b>Miscellaneous</b>		

<b>CORRECTIVE ACTION REQUIRED:</b> <u>May require re-seeding with manure spreader.</u>	
Date Corrective Action Required By: <u>4/97</u>	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

# STATEMENT FROM D.C. DOZER SERVICE

Dale Troutman, Owner  
1403 Fillmore  
Sterling, CO 80751  
(303) 522-0051

In account with:

Peterson Energy Mgmt.  
c/o Ashby Drilling Corporation  
1776 Lincoln St., Suite 810  
Denver, CO 80263

Statement No. 0688

Date April 23, 1997

Authorized by Andy Peterson

Location Sedgwick location  
re-seed

Rig No. \_\_\_\_\_

Date Work Performed 3/28, 4/19, 4/20

=====  
Service Rendered as Follows:

Travel time, re-seed road and location,  
crimp straw, rebuild fence, put up new  
charger

- Tractor
- Seeder
- Backhoe
- Crimper
- Straw spreader
- Spreader
- Seed

<u>Hours</u>	<u>Rate</u>	<u>Amount</u>
--------------	-------------	---------------

\$1,300.00

APR 25 1997  
ASHBY DRILLING CO. INC.

THANKS FOR THE WORK!

Accounts not paid within 30 days from invoice will be charged 1 1/2%  
service charge per month.