

WELL SITE INSPECTION FORM



Well Name GLENN SPAULDING #2 API Number 05 - -  
 Operator BURTON-HAWKS Permit # \_\_\_\_\_  
 Location JES W21-TN-81W County JACKSON  
 Field LONE PINE Inspector R. Van Sickle  
 AL/PA/DA Inspection Results: Well Status:  
 Pass (Y) \_\_\_\_\_ Fail (N) \_\_\_\_\_ Date 8-2-90 FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
 Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
 Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Contact \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
 Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
 Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: \_\_\_\_\_ Date Permit Expired: \_\_\_\_\_  
 Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Bond Release OK: Yes \_\_\_\_\_ No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

Date of Safety/Status Inspection \_\_\_\_\_

Comments: NO SIGN OF THE WELL. CUT W/O PLUGS?  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Violations: Yes \_\_\_\_\_ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_