

RECEIVED 7

NOV 20 1974

J. M. HUBER CORPORATION

385 DENVER CLUB BUILDING
DENVER, COLORADO 80202
OIL AND GAS DIVISION

COLO. OIL & GAS CONS. COMM.

DENVER DISTRICT
222-5611

November 18, 1974

United States Geological Survey
Oil and Gas Operations
8426 Federal Building
125 S. State Street
Salt Lake City, Utah 84138

*Still wrong -
see even newer
change*

Re: Amended Location
Huber-Wainoco
Godiva Rim Unit #30-1
2720' FSL 2340' FEL
Sec. 30-T9N-R95W
Moffat County, Colorado

74-955
SWNE

Gentlemen:

Reference is made to our APPLICATION FOR PERMIT TO DRILL, dated 10-31-74.

An on site inspection of the original proposed location by the surface owner and BLM has prompted a change of the well location to that shown on the attached plot. This is approximately 850' North Northwest of the original site.

The original location would have required a substantial cut in the sloping terrain whereas the new site is on the flat. Also, a gulley crossing can be avoided. It is believed the amended location will be in keeping with the preservation of the area ecology.

Sincerely yours,

J. M. HUBER CORPORATION

R. P. Bixler

R. P. Bixler
District Production Manager

RB/jf

Attachment



00287636