

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404537194

Date Received:  
02/09/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
7 of 7 CAs from the FIR responded to on this Form  
4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10764  
Name of Operator: NUEVIDA RESOURCES LLC  
Address: 5950 CEDAR SPRINGS RD STE #100  
City: DALLAS State: TX Zip: 75235  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>McDonough, Corey</u>		<u>corey.mcdonough@state.co.us</u>
<u>Coleman, Chris</u>		<u>chris.coleman@state.co.us</u>
<u>Pate, Richard</u>		<u>dpate@nuevidaresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714003037  
Inspection Date: 12/12/2025 FIR Submit Date: 12/22/2025 FIR Status:

Inspected Operator Information:

Company Name: NUEVIDA RESOURCES LLC Company Number: 10764  
Address: 5950 CEDAR SPRINGS RD STE #100  
City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 484496

Location Name: Ardourel 33081718 Number: County:  
Qtrqr: Lot 3 Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.101193 Longitude: -107.767596

FACILITY - API Number: 05-067-00 Facility ID: 484496

Facility Name: Ardourel 33081718 Number:  
Qtrqr: Lot 3 Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.101193 Longitude: -107.767596

CORRECTIVE ACTIONS:

1 CA# 210120

Corrective Action: Comply with rule 603.o and Form 2A COA's Date: 01/05/2026

Response: OTHER

Operator Comment: NueVida (NVR) acknowledges that there are several small tears in the liner along the northern berm in the TUA Pad that need repaired. There are no D&C operations ongoing on either the TUA or Well Pads during winter/early spring due to CPW wildlife strips from 12/01 through 04/30 each year. The TUA Pad is inactive & secured with all tanks and equipment off of the location. Cement barriers are set at all entrances to block any

potential traffic onto the Pad. NVR's practice (has been, and) is to inspect and repair the liner during May (2026) prior to any operations that will be conducted on the TUA Pad. Liner repairs in the colder winter months are not preferred as the "welding technique" used has potential to have poor sealing vs warmer operational months. The reason for the liner in the TUA Pad is for the produced water (requirement by CECMC of minimum of 3% produced water in D&C operations) that is stored in a MLVT during stimulation operations. The liner is for containment of produced water in case of a potential MLVT leak and/or liner failure. When the MLVT's are removed at the end of operations each year, the potential for a produce water spill is eliminated and the TUA Pad is then secured.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 210121

Corrective Action: Comply with Rule 406.c Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 12/29/2025

Operator Comment: Refer to attached document: NVR-Forms 2A & 4\_Wellsite Location. Forms are located within binders in a safe/dry place in the CONEX office located on the Well Pad.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 210122

Corrective Action: Comply with Rule 605.e and 605.h Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 01/28/2026

Operator Comment: Signage Installed.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**4** CA# 210123

Corrective Action: Comply with rule 606, remove and properly dispose of all trash and debris stored on the location. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 12/29/2025

Operator Comment: Trash removed.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**5** CA# 210124

Corrective Action: Comply with Rules 1003.f, 606.c and 1002.c. Date: \_\_\_\_\_

Response: OTHER

Operator Comment: Refer to attachment: NVR\_Weed Management Summary-2025. Weed management is an ongoing-yearly process. Active weed management times (growing season) are from May 1 through October 30 each year. Weed management is not conducted in the winter months/early spring (11/15 - 05/01). NVR will continue to manage weeds each year and apply the necessary techniques/tools available to control weed growth - refer to the noted attachment of NVR's weed management activity in 2025.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**6** CA# 210125

Corrective Action: Comply with Rule 902.b.: Install or repair wildlife protection BMPs.

Date: 12/29/2025

Response: CA COMPLETED

Date of Completion: 12/19/2026

Operator  
Comment:

Refer to attachment: NVR\_Wildlife-BMP\_Correction. BMP's repaired.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**7** CA# 210126

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: \_\_\_\_\_

Response: OTHER

Operator  
Comment:

Refer to attachment: NVR\_SWMP-Management Summary 2025. NueVida (NVR) has complied with all necessary SWMP repairs except for the small area in the SW corner of the TUA Pad. The SW area of the TUA Pad noted in the FIR was extremely soft and had water accumulation due to the 6-day storm event (50-year event) that occurred in October 2025. NVR determined that attempting repairs in the SW corner of the TUA Pad would be difficult due to the very wet conditions and could result in damage of the liner as well as create additional erosional problems on the specific slope. In addition, this SW area of the TUA Pad has very good containment of any erosional discharge (soil/water). NVR determined that this SW area of the TUA Pad would not effectively dry out prior to CPW wildlife restrictions (12/01 - 05/01) in order to attempt any repairs. NVR will plan repairs accordingly in May 2026, once wildlife restrictions are lifted and the SW area has dried out sufficiently for proper repairs.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Richard Pate

Signed: \_\_\_\_\_

Title: COO: VP-Engr/Opns

Date: 2/9/2026 7:38:44 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404537199	NVR-Weed Management Program 2025
404537202	NVR_SWMP Management Summary 2025
404537204	NVR_Wildlife-BMP_Correction
404537206	NVR_Form 2A & 4's Wellsite Location

Total Attach: 4 Files