

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2026

Submitted Date:

02/06/2026

Document Number:

713602697

**FIELD INSPECTION FORM**

Loc ID 324800 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10777  
Name of Operator: RAMPIKE RESOURCES LTD  
Address: 730 17TH STREET SUITE 999  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
SHARP, NEIL		nsharp@rampikeresources.com	
		dnr_ecmc_complaints@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324800	LOCATION	AC			-	DAWSON A-619S45W 9SWNW	RI

**General Comment:**

This is a reclamation inspection in regard to complaint #200452252 and #200452254. See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	This inspection was performed in response to complainants concern of conditions of the access roads. There are areas of the main road that are below the original topography grade. There are concerns with winter snow drifting onto the road impeding travel. Best Management Practices will need to be considered to maintain the road in a stable condition and to allow all weather access. BMP's may include: timely snow removal practices, snow fencing, regrading, ect. See Rules 603.I. and 1002.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Per rule 605.g. Upon form 9 approval, the Operator must update signage within 60 days. New Operator name and emergency contact will need to be installed at each well and tank battery site.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 324800 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Complaint**

Comment: [Complaint ID: 200452252](#)  
 Description: erosion of the road has made roads impassable after snow. cattle are forced to walk through or around the areas.  
 Location Of Concern:  
 lat 38.42431 long -102.470

[Complaint ID: 200452254](#)  
 Description: erosion of the road has made roads impassable after snow storms which makes caring for cattle hard. cattle are forced to walk around or through dangerous spots.  
 Location Of Concern:  
 lat 38.41854, long -102.473

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the main roadside that has eroded and is not stabilized. There are sandy soils that are susceptible to further wind and stormwater erosion. The roadside will need to be repaired and stabilized. This area of the road consists of loose sandy soils and appropriate stabilization BMP's such as roadbase aggregate will be needed. See photos 3,4,7,8.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)  
Comply with Rule 1002.e.

Date: 02/20/2026

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404536028	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441860">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441860</a>
713602698	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441856</a>